

BUILDING SAFETY CERTIFICATE

NO. 411

Dated: 28-04-2025

It is certified that the existing building St. Xavier's E – School (name of the building or premises) at Sangat Road, Gurthari Distt. Bathinda (address) is having blocks (s)/ floor (s) as per details below :

Details of Blocks(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of floor(s) in the Block	2	NA	NA	--	--	--

The building is owned/ occupied by St. Xavier's E – School Sangat Road, Gurthari Distt. Bathinda (name of the institution) have complied with the Building Safety Requirements and verified by the officer concerned of Executive Engineer PWD (Name of Department / Govt.) on 25-04-2025 (date of inspection) in the presence of Amit Gupta Bathinda (name and addresses of the Manager / Secretary or his representative) and that the Building / Premises is fit for occupancy for running school with effect from 01-04-2025 for a period of one year (31-03-2026) in accordance with rule and subject to compliance of the specific condition as appended.

1. Fire Safety certificate, electrical safety certificate should be obtained separately from the concerned department.
2. Keeping the safety of the school building as a priority, it is the responsibility of the school management to repair the building. Despite this report, the school management is responsible for the security of the building in all respects.
3. The school must provide staff members with appropriate safety training, including procedures for handling emergency first aid and evacuation protocols.
4. If the walls, foundations and roofs of the building collapse due to natural calamity or any other reason, then the school should immediately inform this office about the condition of the building and the building should be put into use only after conducting an inspection.
5. The school should have a plan to deal with an untoward incident, including the safe evacuation of children from the building during an emergency and a plan to coordinate with the concerned department. The school should regularly review and update this plan to ensure its effectiveness.
6. If any addition, alteration, expansion and modification is required or to be done by the school in this building, then an immediate inspection should be arranged by this office and its safety certificate should not be obtained from this office again after completion of that part.
7. Er. Sandeep Singh Romana Bathinda, B.Tech (Civil) Bainse Bhatinda 02.04.2025 8 Matwabachat Murtadhibha Matti Debate has been approved and according to their certificate the school is safe for the session 2025-26, but this school is not constructed by this department so the safety of the school structure especially from earthquake point of view cannot be ensured by this department.
8. According to the covered area of the school, G.R. 1744759 dated 16.04.2025 vide ten thousand rupees (10,000/ received as a building inspection fee. The school management will be responsible for renewing the fire safety certificate within the time limit.

Issued on 28-04-2025 at PWD office Bathinda by Executive Engineer

*Strike out whichever is not applicable. In case of block is more than six use separate sheet for details.

Signature with Seal:.....

Name:
Executive Engineer

Designation:
Construction Div.No. 2
PWD BSR Br. Bathinda

Name & Address of Department / office: